

Errata

<Document Name>

QB-8 Family Design Manual Ver.2.0 User's Manual

<Document No., Date Published>

A10936EJ2V0UM00 (2nd Edition) November 1998 N

<Location of Error>

p. 130 **4.6.6 Simultaneous switching limit determination method**
Calculation example 1, No.3

<Description>

Change the value of underlined part.

<Error>

- Conversion coefficient for number of simultaneous switching pins: 18.0 mA,
3-V output → 1.48

<Correction>

- Conversion coefficient for number of simultaneous switching pins: 18.0 mA,
3-V output → 1.30